

Inspection Photos
Location Name: KW Location
Location ID: 333316



Photo 1: Centralized Tank Battery



Photo 2: Stained soil



Inspection Photos
Location Name: KW Location
Location ID: 333316



Photo 3: Trash in gas meter house.



Photo 4: Unused equipment



Inspection Photos
Location Name: KW Location
Location ID: 333316



Photo 5: Unused equipment



Photo 6: Unused equipment

Inspection Photos
Location Name: KW Location
Location ID: 333316



Photo 7: Unused equipment