

Inspection Photos

Location Name: JAMIE LEE 33-7-9 #3B

API #: 05-067-09612

INSP. #:695100642



PHOTO 1: WELL SIGN



PHOTO 2: TANK BATTERY/ NFPA STICKER IS
FADED AND IS NOT LEGIBLE. **Install sign to
comply with Rule 210. CA DATE 6/21/19**



Inspection Photos

Location Name: JAMIE LEE 33-7-9 #3B

API #: 05-067-09612

INSP. #:695100642



Colorado Oil & Gas Conservation Commission
37.11418, -107.60843, 1994.0m, 305°
2019/05/14 10:19:09



Colorado Oil & Gas Conservation Commission
37.11419, -107.60819, 1992.0m, 351°
2019/05/14 10:22:57

PHOTO 3: WELL SIGN

**PHOTO 4: TRASH INSIDE BERM FOR
PRODUCED WATER TANK. REMOVE TRASH TO
COMPLY WITH RULE 603.f. CA DATE 6/21/19**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: JAMIE LEE 33-7-9 #3B

API #: 05-067-09612

INSP. #:695100642



PHOTO 5: IMPACTED SOIL AROUND THE 33-7-9 #1 WELLHEAD. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907" CA DATE 6/21/19

PHOTO 6: IMPACTED SOIL AROUND NORTH SIDE OF THE 33-7-9 #1 PUMPJACK MOTOR. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907" CA DATE 6/21/19

Inspection Photos

Location Name: JAMIE LEE 33-7-9 #3B

API #: 05-067-09612

INSP. #:695100642



PHOTO 7: APPEARS TO BE RUST OR SCALE PILED NEXT TO PUMPJACK SKID ON THE 33-7-9 #3B WELL. REMOVE TRASH TO COMPLY WITH 603.f. CA DATE 6/21/19



PHOTO 8: IMPACTED SOIL AROUND EAST OF THE 33-7-9 #3B WELLHEAD. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2), 907 & 906" CA DATE 6/21/19

Inspection Photos

Location Name: JAMIE LEE 33-7-9 #3B

API #: 05-067-09612

INSP. #:695100642



PHOTO 9: LABEL ON CHEM. CONTAINER NEAR WELL 33-7-9 #3B IS FADED AND NOT LEGIBLE. COMPLY WITH RULE 210. CA DATE 6/21/19



PHOTO 10: LABEL ON CHEM. CONTAINER NEAR WELL 33-7-9 #1 IS FADED AND NOT LEGIBLE. COMPLY WITH RULE 210. CA DATE 6/21/19



Inspection Photos

Location Name: JAMIE LEE 33-7-9 #3B

API #: 05-067-09612

INSP. #:695100642



PHOTO 11: LABEL ON CHEM. CONTAINER NEAR METER HOUSE ON NORTHEAST EDGE OF LOCATION IS FADED AND NOT LEGIBLE. COMPLY WITH RULE 210. CA DATE 6/21/19



PHOTO 12: There is a dark oily fluid in the spill prevention by the meter house. **Comply with SB-181 and general provisions of the oil and gas act for wildlife protection. CA date 5/21/19.**

