

Inspection Photos
Location Name: ALABASTER 11-8
API #: 05-071-08642
INSP. #:695100657



Colorado Oil & Gas Conservation Commission
37.18951, -104.81147, 2190.0m, 311°
2019/05/20 12:33:29



Colorado Oil & Gas Conservation Commission
37.18933, -104.81154, 2184.0m, 210°
2019/05/20 12:33:15

PHOTO 1: WELLHEAD

PHOTO 2: WELL SIGN DOES NOT DEPICT CURRENT OPERATOR. COMPLY WITH RULE 210. CA DATE 7/20/19

Inspection Photos

Location Name: ALABASTER 11-8

API #: 05-071-08642

INSP. #:695100657



PHOTO 3: Hydraulic Stained soil at base of wellhead approx 6'x 3'. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Remove or remediate stained soil. Ca date 6/20/19



PHOTO 4: Engine skid stained soil around skid. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Remove or remediate stained soil. Ca date 6/20/19

Inspection Photos

Location Name: ALABASTER 11-8

API #: 05-071-08642

INSP. #:695100657



PHOTO 5: Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible. No capacity posted NFPA sign has no numbers. **Install sign to comply with Rule 210.d. ca date 7/20/19**