

Inspection Photos
Location Name: WHARTON 33-32
API #: 05-071-06296
INSP. #:695100659



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN IS NOT DEPICTING CURRENT
OPERATOR. **COMPLY WITH RULE 210. CA DATE 7/20/19**



Inspection Photos
Location Name: WHARTON 33-32
API #: 05-071-06296
INSP. #:695100659



PHOTO 3: AREA OF IMPACTED SOIL APPROX. 3' x 2' NEAR WELLHEAD. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. CA DATE 6/20/19