

**Inspection Photos**  
**Location Name: MARBLE 34-33**  
**API #: 05-071-09377**  
**INSP. #:695100661**



**PHOTO 1: WELLHEAD**



**PHOTO 2: WELL SIGN**



Inspection Photos  
Location Name: MARBLE 34-33  
API #: 05-071-09377  
INSP. #:695100661



**PHOTO 3: UNUSED EQUIPMENT (1 JT OF 2" PIPE LYING NEXT TO WELLHEAD. COMPLY WITH RULE 603.f. CA DATE 6/20/19**



**PHOTO 4: AN AREA APPROX. 6' LONG BY 2' WIDE OF IMPACTED SOIL EAST OF WELLHEAD. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. CA DATE 6/20/19**