

Inspection Photos
Location Name: Cody 44-11v
API #: 05-071-08192
INSP. #:695100678



PHOTO 1: wellhead

PHOTO 2: WELL SIGN

Inspection Photos
Location Name: Cody 44-11 R
API #: 05-071-08872
INSP. #:695100680



PHOTO 3: Vacuum pump observed on well without COGCC approval. Provide COGCC with documentation showing approval of use of vacuum pump. CA DATE 6/5/19