

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2019

Submitted Date:

05/23/2019

Document Number:

692601933**FIELD INSPECTION FORM**
 Loc ID 321607 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10713Name of Operator: DARRAH OIL COMPANY LLCAddress: 125 N MARKET STE 1425City: WICHITA State: KS Zip: 67202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Atterbury, Mike	(316) 219-3390	mike.atterbury@darrahoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207482	WELL	PR	01/12/1984	OW	017-06417	CHAMPLIN 205 AMOCO A 4	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Graveled two track through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	Lufkin 320		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Electric panel and cathodic rectifier		
Corrective Action:		Date:	

Venting:

Yes/No	YES		
Comment:	2" Casing vent		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	207482	Type:	WELL	API Number:	017-06417	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Central tank batery for (Champlin 205 Amoco A-2, A-4, A-5) 2630' W @ 38.723500/-102.533240								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT