

Inspection Photos

Loc#419862

Operator: Terra

Inspection Number: 692401004

Inspection Date: 5/21/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southwest.

May 21, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Mead Loc#419862



Photo#2

Majority of the interim reclamation areas appear to be an almost monoculture of Cheat grass.

May 21, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Mead Loc#419862



Photo#3:
Hayfield portion of Interim Reclamation.



Photo#4:
Erosion in Hayfiel area.

May 21, ,2019



Photo#5:
Erosion on Cut Slope.



Photo#6:
Sediment migrating from Cut slope.

May 21, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Mead Loc#419862



Photos#7:

Sediment appears to be coming from erosion of channel itself; not the Pad above.

May 21, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Mead Loc#419862



Photo#8:
Dead Annual Weeds that have broken off and become
Debris.



Photo#9:
Dead Annual Weeds that have broken off and become
Debris.

May 21, ,2019