

Inspection Photos

Loc#335537

Operator: Ursa

Inspection Number: 692401015

Inspection Date: 5/22/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Unused Equipment.

May 22, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Loc#335537



Photo#2:
Uncovered Rat/Mouse Hole?.

May 22, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Loc#335537