

Inspection Photos  
Location Name: SE Spargo #1  
API: 05-033-06118



Location sign with Seeley Oil Company listed as the operator.



SE Spargo #1 location photo.

**Inspection Photos**  
**Location Name: SE Spargo #1**  
**API: 05-033-06118**



**Compressor building and gravel stained with oil.**



**Inside of compressor building.**



**Inspection Photos**  
**Location Name: SE Spargo #1**  
**API: 05-033-06118**



**Concrete pad and gravel are stained beneath prime mover.**



**Open topped produced water/crude oil vessel.**



**Inspection Photos**  
**Location Name: SE Spargo #1**  
**API: 05-033-06118**



**Fluid level up to edge of vessel.**



**Stained soil in SE corner of vessel. Contents are overflowing.**



**Inspection Photos**  
**Location Name: SE Spargo #1**  
**API: 05-033-06118**



**Contents of open topped vessel are overflowing.**



**SE Spargo #1 tank battery.**