

Inspection Photos
Location Name: PEPPLER-66N63W /18SESE
Location #: 305864



Photo #1

Peppler 18-44 (05-123-23595) Wellsite
Temporarily Abandoned | TA



Photo #2

Peppler 18-41, 18-44 Battery site
Abandoned – ALL equipment removed
Reclamation progressing