

Inspection Photos

Location ID: 302455



Photo 1 Overview of Well Shack Battery and Truck Used for MIT Testing



Photo 2 Initial Bradenhead Pressure Gauge



Photo 3 Initial Casing Pressure Gauge