

Inspection Photos

Location Name: PEPPLER-66N63W /17SWNW

Location #: 310651



Photo #1

Peppler 17-12 (05-123-26749) Wellsite

Shut-In | SI

Emergency Number NOT posted
from prior insp.



Photo #2

Peppler 17-12 Wellsite

Shut-In | SI

Emergency Number NOW posted

Inspection Photos
Location Name: PEPPLER-66N63W /17SWNW
Location #: 310651



Photo #3
Peppler 17-12, 17-22 Battery
Shut-down
Illegible capacity – Condensate tanks
from prior insp.



Photo #4
Peppler 17-12, 17-22 Battery
Shut-down
Condensate tanks – Capacity NOW Legible

Inspection Photos
Location Name: PEPPLER-66N63W /17SWNW
Location #: 310651



Photo #5
Peppler 17-12, 17-22 Battery
East condensate tank - loadout
Stained soil
from prior insp.



Photo #6
Peppler 17-12, 17-22 Battery
East condensate tank - loadout
Stained soil – Appears Mitigated

Inspection Photos
Location Name: PEPPLER-66N63W /17SWNW
Location #: 310651



Photo #7
Peppler 17-12, 17-22 Battery
West condensate tank - loadout
Stained soil
from prior insp.



Photo #8
Peppler 17-12, 17-22 Battery
West condensate tank - loadout
Stained soil – Appears Mitigated