

Inspection Photos
Location Name: PEPPLER-66N63W /17SENW
Location #: 310057



Photo #1
Peppler 17-22 (05-123-25817) Wellsite
Shut-In | SI
Emergency Number NOT posted
from prior insp



Photo #2
Peppler 17-22 Wellsite
Shut-In | SI
Emergency Number NOW posted

Inspection Photos
Location Name: PEPPLER-66N63W /17SENW
Location #: 310057



Photo #3
Peppler 17-12, 17-22 Battery
Shut-down
Illegible capacity – Condensate tanks
from prior insp.



Photo #4
Peppler 17-12, 17-22 Battery
Shut-down
Condensate tanks – Capacity NOW Legible