

Inspection Photos  
Location Name: Spargo #2  
API: 05-033-06093



Spargo #2 location sign with Seeley Oil Company contact information on it.



RW Trucking water hauler transferring produced water from Spargo #1-36.

**Inspection Photos**  
**Location Name: Spargo #2**  
**API: 05-033-06093**



**Spargo #2 location photo.**



**Drip pot at truck load out.**

**Inspection Photos**  
**Location Name: Spargo #2**  
**API: 05-033-06093**



**Open topped buried vessel labeled produced water.**



**Spargo #2 well head.**