

**MARALEX RESOURCES, INC.– 53255**  
**API# 05-067-06460 MAGDALEN CLARE 33-7-2 #2**  
**Inspection Date : 05/14/2019**



**Overview of location from W side deadman marker looking E.**



**Wellhead with sign**

**MARALEX RESOURCES, INC.– 53255**  
**API# 05-067-06460 MAGDALEN CLARE 33-7-2 #2**  
**Inspection Date : 05/14/2019**



**Separator, meter housing and domestic taps.**



**Blowdown tank with fencing and sign.**

**MARALEX RESOURCES, INC.– 53255**  
**API# 05-067-06460 MAGDALEN CLARE 33-7-2 #2**  
**Inspection Date : 05/14/2019**



**Disconnected and unused flowline on W side of meter housing  
needs removal**



**Unused riser E. of equipment**

**MARALEX RESOURCES, INC.– 53255**  
**API# 05-067-06460 MAGDALEN CLARE 33-7-2 #2**  
**Inspection Date : 05/14/2019**



**Riser for off location gathering line.**



**Separator vent with no bird screen.**

**MARALEX RESOURCES, INC.– 53255**  
**API# 05-067-06460 MAGDALEN CLARE 33-7-2 #2**  
**Inspection Date : 05/14/2019**



**Active bird nest inside separator housing**