

Maralex Resources Inc.  
API # 05-077-08496  
Inspection # 696600058



Photo at wellhead.

Maralex Resources Inc.  
API # 05-077-08496  
Inspection # 696600058



Location photo



Wellhead photo from south deadman



Maralex Resources Inc.  
API # 05-077-08496  
Inspection # 696600058



Photo of location at entrance



Photo of location from north deadman



Maralex Resources Inc.  
API # 05-077-08496  
Inspection # 696600058



**Dry fenced pit**



**Dry fenced pit**



**Maralex Resources Inc.**  
**API # 05-077-08496**  
**Inspection # 696600058**



**Only a wellhead and 2 deadmen on location along with a dry fenced pit**



**Only a wellhead and 2 deadmen on location along with a dry fenced pit**



Maralex Resources Inc.  
API # 05-077-08496  
Inspection # 696600058



**Fire pit by dead man**



**Fire pit looking toward wellhead (Left of pickup)**