

Inspection Photos

API: 05-071-07968

Operator: PRESCO INC

Inspection Date: 5/24/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 5/24/2019

Inspection Photos



Photo 1. Facing northeast toward the location. The area circled is predominately weeds (Kochia).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 5/24/2019

Inspection Photos



Photo 2. Facing south. A shallow pit remains per approved variance request.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 5/24/2019

Inspection Photos



Photo 3. Facing south at the location. Rip/rap is placed in drainage channel.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 5/24/2019

Inspection Photos



Photo 4. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 5/24/2019

Inspection Photos



Photo 5. There is noxious weeds at the location. Scotch thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 5/24/2019

Inspection Photos



Photo 6. There is noxious weeds at the location. Hounds tongue.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 5/24/2019