

# Inspection Photos

API: 05-071-07969

Operator: PRESCO INC

Inspection Date: 5/24/2019




**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-071-07969 | Date: 5/24/2019

## Inspection Photos



**Photo 1.** Aerial map shows the beginning of the access road developed for the well site. Previously did not exist.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 5/24/2019

## Inspection Photos



**Photo 2.** Facing toward the access road to the well site. Near the beginning of the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 5/24/2019

## Inspection Photos



**Photo 3.** Facing southeast along the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 5/24/2019

## Inspection Photos



**Photo 4.** Facing northeast along the reclaimed portion of the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 5/24/2019

## Inspection Photos



**Photo 5.** Facing north toward the location. Vegetation is well established and consist of Bro ine, Pas smi.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 5/24/2019

## Inspection Photos



**Photo 6.** Facing east toward the location. A shallow pit remains per approved variance request.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07960 | Date: 5/24/2019