

Inspection Photos  
Operator: BP America  
Location/API #: 067-08945  
Date: 5-20-2019



Photo 1. View of the project area from the northeastern corner facing center.





Photo 2. View of example of waste material within the interim reclamation area.





Photo 3. View of erosional channels approximate 2 feet wide and 1 foot deep within the southern project area.





Photo 4. View of reference area north of project area.