

Inspection Photos
Loc#334687
Operator: Caerus
Insp#692400996
Inspection Date: 5/21/2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

May 21, 2019

Inspection Photos: Encana Savage Federal
Loc#334687



Photo#1:
Overview of Location.

May 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Savage Federal Loc#334687



Photo#2:
Location appears well maintained and Vegetation in Interim Reclamation areas well established.

May 21, 2019