

Construction and Stormwater Inspection

May 24, 2019

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 456769

Inspection Document #: 697500158

Broomfield County, CO

NWNW Section 9 T1S R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: NORTHWEST A PAD
Location ID: 456769



Photo 1. Photo taken from the southwestern perimeter of the location, facing West. A berm BMP has been installed around the perimeter of the location but it has not been installed with good engineering practices. The berm BMP has not been stabilized. Note: Other disturbances in the foreground are not associated with oil and gas operations.

Inspection Photos
Location Name: NORTHWEST A PAD
Location ID: 456769



Photo 2. Photo taken from the southwestern perimeter of the location, facing Northwest. Operator has only initiated stormwater implementation and has not yet started topsoil salvage operations.