

Inspection Photos
Location Name: Maier #4B-28H
Location ID: 433035



Pic 1



Pic 2 stained water in cellar/wellhead area

Inspection Photos
Location Name: Maier #4b-28H
Location ID: 433035



Pic 3 stained water/weeds



Pic 4 stained water/weeds

Inspection Photos

Location Name:

Location ID:



Pic 5 comparison of standing water on location

Pic 6

Inspection Photos

Location Name:

Location ID:



Pic 7

Pic 8