

Inspection Photos

Location Name: GARCIA-61S69W 1SESW/ GARCIA UPRR 31-51-1 Pit

Location ID 321325/ Pit Facility ID 114872



Photo 1 – Battery location sign



Photo 2 – Location photo; concrete vault on site



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: GARCIA-61S69W 1SESW/ GARCIA UPRR 31-51-1 Pit

Location ID 321325/ Pit Facility ID 114872



Photo 3 – Location photo



Photo 4 – Stained soil at separator



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: GARCIA-61S69W 1SESW/ GARCIA UPRR 31-51-1 Pit

Location ID 321325/ Pit Facility ID 114872



Photo 5 – 1993 aerial imagery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: GARCIA-61S69W 1SESW/ GARCIA UPRR 31-51-1 Pit

Location ID 321325/ Pit Facility ID 114872



Photo 6 – 2002 aerial imagery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: GARCIA-61S69W 1SESW/ GARCIA UPRR 31-51-1 Pit

Location ID 321325/ Pit Facility ID 114872



Photo 7 – 2018 aerial imagery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources