

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-09601**  
**Date: 5-20-2019**



Photo 1. View of the southern project area from the southwestern corner facing eastward.



Photo 2. View of Canada thistles (*Cirsium arvense*) within the interim reclamation area.



Photo 3. View of pond within the northeastern project area.