

Inspection Photos

Loc#336022

Operator: Ursa

Inspection Number: 692401019

Inspection Date: 5/22/19





Photo#1:
Unused Equipment.

May 22, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Loc#336022



Photo#2:
Flooded Cellars.

May 22, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Loc#336022