

*Inspection Photos*  
*Loc#324224*  
*Operator: Caerus*  
*Insp#692401024*  
*Inspection Date: 5/22/2019*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

May 21, 2019

Inspection Photos: Caerus Aspen Loc#  
324224



Photo#1:  
Overview of Location.

May 21, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Aspen Loc# 324224



Photo#2:  
Location appears well maintained and Vegetation in Interim Reclamation areas well established.

May 21, 2019