

**Inspection Photos**  
**Location Name:** BASHOR PC /AA17-23  
**Location #:** 306260



**Photo #1**

**Bashor PC AA17-23 (05-123-24320) Wellsite**  
**Temporarily Abandoned | TA**



**Photo #2**

**Bashor PC AA17-15, 16, 21, 22, 23, 24, Bashor 17-13,**  
**Bashor 17-41, Peppler PC AA17-20 – Battery Site**  
**Abandoned – ALL equipment removed**  
**Muddy w/ puddles**  
**Reclamation progressing**