

Inspection Photos
Location Name: BASHOR PC /AA17-15
Location #: 306263



Photo #1

Bashor PC AA17-15 (05-123-24323) Wellsite
Temporarily Abandoned | TA



Photo #2

Bashor PC AA17-15, 16, 21, 22, 23, 24, Bashor 17-13,
Bashor 17-41, Peppler PC AA17-20 – Battery Site
Abandoned – ALL equipment removed
Muddy w/ puddles
Reclamation progressing