

Inspection Photos
Location Name: CARIBOU 42-32
API #: 05-071-08763
INSP. #:695100719




PHOTO 1: WELLHEAD

PHOTO 2: WELL SIGN/ CURRENT OPERATOR NOT POSTED. **POST CURRENT OPERATOR SIGN IN ACCORDANCE WITH RULE 210. CA DATE 7/28/19**

Inspection Photos
Location Name: CARIBOU 42-32
API #: 05-071-08763
INSP. #:695100719



PHOTO 3: TRASH INSIDE WELLHEAD HOUSE. REMOVE TRASH IN ACCORANCE WITH RULE 603.f. CA DATE 6/7/19.

PHOTO 4: RUN ON BMP FULL WITH SEDIMENT. CLEAN SEDIMENT FROM BMP IN ACCORANCE WITH RULE 1002. CA DATE 6//28/19.

Inspection Photos
Location Name: CARIBOU 42-32
API #: 05-071-08763
INSP. #:695100719



PHOTO 5: RUN ON BMP FAILURE. REPAIR RUN ON BMP IN ACCORDANCE WITH RULE 1002. CA DATE 6/28/19