




Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	May 22, 2019 12:16:48 PM MDT
Server Receive Date:	May 22, 2019 2:11:28 PM MDT
Reference Number:	20190522-18107176101
Location:	Unknown Location

Information

Name	celkins@gobrainstorm.net
Date	May 16, 2019
Well Name	MCCAW GAS UNIT C 2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean up Operator Debris Clean Up Land Owner Debris Removed sediment from BMP's

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos

