

**Inspection Photos**  
**Location Name: Bower Location**  
**Location ID: 431721**



**Photo 1: Tank Battery**



**Photo 2: BBLs not legible on produced water tank.**