

Inspection Photos
Location Name: Gutterson 5-1
Location ID: 323374



Photo 1: Wellhead



Photo 2: Tank Battery

Inspection Photos
Location Name: Gutterson 5-1
Location ID: 323374



Photo 3: Disconnected separator.