

Inspection Photos
Location Name: BASHOR PC /AA17-24
Location #: 419444



Colorado Oil & Gas Conservation Commission
40.48291, -104.46023, 1403.0m, 63°
05/28/2019 02:18:51 PM

Photo #1

Bashor PC AA17-24 (05-123-32256) Wellsite
Temporarily Abandoned | TA



Colorado Oil & Gas Conservation Commission
40.4846, -104.46046, 1408.0m, 326°
05/28/2019 02:22:48 PM

Photo #2

Bashor PC AA17-15, 16, 21, 22, 23, 24, Bashor 17-13,
Bashor 17-41, Peppler PC AA17-20 – Battery Site
Abandoned – ALL equipment removed
Muddy w/ puddles
Reclamation progressing