

Inspection Photos
Location Name: PEPPLER PC /AA17-20
Location #: 419494



Photo #1

Peppler PC AA17-20 (05-123-32266) Wellsite
Temporarily Abandoned | TA
Emergency number Incorrect



Photo #2

Bashor PC AA17-15, 16, 21, 22, 23, 24, Bashor 17-13,
Bashor 17-41, Peppler PC AA17-20 – Battery Site
Abandoned – ALL equipment removed
Muddy w/ puddles
Reclamation progressing