



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Cole Nichols (colen@horizonenvservices.com)
Submission Date: May 10, 2019 1:14:43 PM MDT
Server Receive Date: May 10, 2019 1:16:01 PM MDT
Reference Number: 20190510-18105938221
Location: 557 Airpark Dr, Durango, CO 81303, USA
May 10, 2019 1:15:46 PM MDT [[View Map](#)]

Information

Name colen@horizonenvservices.com
Date May 9, 2019
Well Name JONES, EVERETT GAS UNIT 1
Location Name (Other) Jones, Everett Gas Unit 2
API Number 50670737900
Select State Colorado
Work type COGCC Inspection AR
Action Complete Clean Up Weed Debris
Picture North to South



Picture South to North



Picture East to West



Picture West to East



Completed work description

mowed and removed weed debris