

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/29/2019

Submitted Date:

05/29/2019

Document Number:

690003621

FIELD INSPECTION FORM

Loc ID 336490 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289742	WELL	PR	11/01/2018	GW	123-24911	ST. ACACIUS 18-35	PA

General Comment:

Location

Overall Good:

Signs/Marker:

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 289742 Type: WELL API Number: 123-24911 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Schumberger Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): 155

Good Return During Job: YES Cement Type: G

Comment: Safety meeting held prior to pumping cement.
 Retainer set at 2660 ft.
 Holes at 2600-2604 ft., 3000-3002 ft.
 155 Sacks, 42.7 Bbls

Corrective Action: _____ Date: _____

Workover

Comment: BASIC 1662

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
On Wednesday, May 29, 2019 at 12:47, I, Craig Carlile conducted an on-site inspection at: 336490, Operated by: Anadarko, company representative, Traux Deal While there I observed: PA operations, cement pumping – 155 sacks at 2660 ft. Weather: Skies overcast, ground wet, winds calm, temp 56 F Possible compliance issues observed: None This is a summary of the inspection report.	carlilec	05/29/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690003622	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4834444