

# Final Reclamation Inspection

May 24, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 330815

Inspection Document #: 697500165

Weld County, CO

NWNW Section 12 T1N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HSR PANORAMA #4-12  
Location ID: 330815



**Photo 1.** Photo taken from the well location, facing East. Unable to find evidence of oil and gas activities and/or disturbances. Well location is part of an active yard for a building company.



**Photo 2.** Photo taken from the well location, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: HSR PANORAMA #4-12  
Location ID: 330815



**Photo 3.** Photo taken from the southwest offsite tank battery location, facing South. Operator has failed to remove all equipment per Rule 1004.

Inspection Photos  
Location Name: HSR PANORAMA #4-12  
Location ID: 330815



**Photo 4.** Photo taken of the equipment left at the tank battery location- see comments under Photo 3.

Inspection Photos  
Location Name: HSR PANORAMA #4-12  
Location ID: 330815



**Photo 5.** Photo taken from the western tank battery location, facing Northwest. Operator shall make repairs to ruts and any other associated disturbance when removing the remaining equipment.