

Final Reclamation Inspection

May 24, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 318702

Inspection Document #: 697500167

Weld County, CO

SENE Section 11 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Cochran USX UU #11-8
Location ID: 318702



Photo 1. Photo taken from the well/facility location, facing East. This location is not in compliance with Rule 1004 vegetative standards. Location is dominated by weedy, annual vegetation (Kochia).



Photo 2. Photo taken from the well/facility location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: Cochran USX UU #11-8
Location ID: 318702




Photo 3. Close up photo of weedy, annual vegetation (Kochia).

Inspection Photos
Location Name: Cochran USX UU #11-8
Location ID: 318702



Photo 4. Photo taken from the western well/facility location, facing Northwest. Photo illustrates reference area vegetative conditions which is not reflective of disturbance areas.

Inspection Photos
Location Name: Cochran USX UU #11-8
Location ID: 318702



Photo 5. Photo taken from the northeastern well/facility location, facing East. Operator has failed to remove equipment from location.