

Interim Reclamation and Stormwater Inspection

May 24, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP- #47120

Location ID: 450677

Inspection Document #: 697500173

Weld County, CO

SWNE Section 11 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: COCHRAN /2N-2HZ
Location ID: 450677



Photo 1. Photo taken from the southern location, facing North. Appears the Operator is in process of performing Interim Reclamation activities.



Photo 2. Photo taken from the southern location, facing East. See comments under Photo 1.