

Inspection Photos
Operator: BP America
Location/API #: 067-09822
Date: 5-23-2319



Photo 1. View of the northern project area from the northwestern corner facing eastward. Vegetation is dominated by a dense population of claspig pepperweed (*Lepidium perfoliatum*) that is competing with desirable vegetation established and needs to be controlled.



Photo 2. View of musk thistle (*Carduus nutans*) within the interim reclamation area.