

**Inspection Photos**  
**Location Name: Magnuson Location**  
**Location ID: 428210**



**Photo 1: Tank Battery**



**Photo 2: Trash inside gas meter house.**



**Inspection Photos**  
**Location Name: Magnuson Location**  
**Location ID: 428210**



**Photo 3: Separator with tubing inside housing.**



**Photo 4: Tubing inside separator house.**



**Inspection Photos**  
**Location Name: Magnuson Location**  
**Location ID: 428210**



Colorado Oil and Gas Conservation Commission  
40.55369, -104.75236, 1476.4m, 238°  
May 29, 2019 15:06:02

**Photo 5: Separator with trash inside housing.**



Colorado Oil and Gas Conservation Commission  
40.5537, -104.75252, 1474.6m, 113°  
May 29, 2019 15:04:54

**Photo 6: Tubing inside separator house.**

