

Inspection Photos

API#045-07675

Operator: Mustang Resources

Inspection Number: 692400995

Inspection Date: 5/21/19





Photo#1:
View over Location from entry.

May 21, ,2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Mustang Res API#045-07675



Photo#2:
Unused area at Northwest end of Pad.



Photo#3:
Unused area at Northwest end of Pad

May 21, ,2019



Photo#4:
Vegetation in existing Interim Rec areas is well established and robust.

May 21, ,2019