

Inspection Photos
Location Name: BASHOR PC AA /17-17
Location #: 419808



Photo #1

Bashor PC AA 17-17 (05-123-32357) Wellsite
Temporarily Abandoned | TA
Unused chemical tank



Photo #2

Bashor 17-11, 17-14
Bashor PC AA 17-17 – Battery Site
Abandoned – ALL equipment removed
Muddy w/ puddles
Reclamation progressing