

Inspection Photos
Location Name: LITTLE JOE 32-26
API #: 05-071-07871
INSP. #:695100731



PHOTO 1: WELLHEAD



PHOTO 2: CURRENT OPERATOR NOT POSTED ON WELL SIGN.
CHANGE OPERATOR NAME TO CURRENT OPERATOR IN
ACCORDANCE WITH RULE 210. CA DATE 7/28/19



Inspection Photos

Location Name: LITTLE JOE 32-26

API #: 05-071-07871

INSP. #:695100731



PHOTO 3: PIT APPEARS TO BE INADEQUATE TO MAINTAIN A 2' FREEBOARD. RECLAIM OR DEEPEN PIT TO MAINTAIN 2' FREEBOARD WHILE IN USE IN ACCORDANCE WITH 902 SERIES RULES. 7/28/19.