

Inspection Photos May 29, 2019

Location Name: Becker Ranch #3 Land Application Area – Spill/Release Inspection (Spill Point #464686)
SESW Section 5 – Township 3 North - Range 64 West
Weld County



Becker 15-7 Tank Battery.



LAA photo looking south.

Inspection Photos May 29, 2019

**Location Name: Becker Ranch #3 Land Application Area – Spill/Release Inspection (Spill Point #464686)
SESW Section 5 – Township 3 North - Range 64 West
Weld County**



LLA photo looking southwest



LLA photo looking west

Inspection Photos May 29, 2019

**Location Name: Becker Ranch #3 Land Application Area – Spill/Release Inspection (Spill Point #464686)
SESW Section 5 – Township 3 North - Range 64 West
Weld County**



Panorama view from north (top right) to south (bottom right). Very wet conditions. Note SW BMP .



Inspection Photos May 29, 2019

**Location Name: Becker Ranch #3 Land Application Area – Spill/Release Inspection (Spill Point #464686)
SESW Section 5 – Township 3 North - Range 64 West
Weld County**



Repaired water damage on BMP and road access southeast side of LLA. Photo looking south



Inspection Photos May 29, 2019

**Location Name: Becker Ranch #3 Land Application Area – Spill/Release Inspection (Spill Point #464686)
SESW Section 5 – Township 3 North - Range 64 West
Weld County**



Location of breached BMP showing residual standing water and recent repair. Photo looking west. Next photo from red circled area.



**Off-site release location.
Photo looking south.**

Inspection Photos May 29, 2019

**Location Name: Becker Ranch #3 Land Application Area – Spill/Release Inspection (Spill Point #464686)
SESW Section 5 – Township 3 North - Range 64 West
Weld County**



Release from off-location looking north onto LLA. Note grey bentonite material.



Detail of water showing bentonite material.