

**Inspection Photos**  
**Location Name: NICKERSON-67N58W /18SWNW**  
**Location #: 326976**



**Photo #1**  
**Nickerson 4 (05-123-13962) Wellsite**  
**Shut-In | SI**



**Photo #2**  
**Nickerson 4 Battery**  
**Shut-down**

**Inspection Photos**  
**Location Name: NICKERSON-67N58W /18SWNW**  
**Location #: 326976**



**Photo #3**  
**Nickerson 4 - Battery sign**  
**Phone number – Not Valid**  
*from prior insp.*



**Photo #4**  
**Nickerson 4 - Battery sign**  
**Phone number – New & Valid**

**Inspection Photos**  
**Location Name: NICKERSON-67N58W /18SWNW**  
**Location #: 326976**



Colorado Oil & Gas Conservation Commission  
40.57644, -103.91415, 1463.0m, 161°  
2018/08/20 03:20:43 PM

**Photo #5**  
**Nickerson 4 - Containers**  
**Placarding is illegible**  
*from prior insp.*



Colorado Oil & Gas Conservation Commission  
40.57644, -103.91415, 1461.0m, 31°  
05/30/2019 12:21:05 PM

**Photo #6**  
**Nickerson 4 - Containers**  
**Placarding is Legible**  
**Has SDS – Safety Data Sheets**

## Inspection Photos

Location Name: NICKERSON-67N58W /18SWNW

Location #: 326976



**Photo #7**

**Nickerson 4 – Separator**

**No wildlife protection screen**

*from prior insp.*



**Photo #8**

**Nickerson 4 – Separator**


**Wildlife protection screen**

**NOW installed**

**Inspection Photos**  
**Location Name: NICKERSON-67N58W /18SWNW**  
**Location #: 326976**



**Photo #9**  
**Nickerson 4 - Engine House**  
**Stained soil around engine base**  
*from prior insp.*



**Photo #10**  
**Nickerson 4 - Engine House**  
**Stained soil around engine base**  
**Appears NOT addressed**

**Inspection Photos**  
**Location Name: NICKERSON-67N58W /18SWNW**  
**Location #: 326976**



**Photo #11**  
**Nickerson 4 – Pit North side**  
**Gaps under framing / netting**  
*from prior insp.*



**Photo #12**  
**Nickerson 4 – Pit North side**  
**Gaps under framing / netting**  
**Appears NOT addressed**

**Inspection Photos**  
**Location Name: NICKERSON-67N58W /18SWNW**  
**Location #: 326976**



**Photo #13**  
**Nickerson 4 – Pit South side**  
**Gaps under framing / netting**  
*from prior insp.*



**Photo #14**  
**Nickerson 4 – Pit South side**  
**Gaps under framing / netting**  
**Appears NOT addressed**