

Inspection Photos
Location Name: Lind 23-15
Location ID: 414362



Photo 1: Wellhead



Photo 2: Tank Battery



Inspection Photos
Location Name: Lind 23-15
Location ID: 414362



Photo 3: Unused riser.



Photo 4: Battery sign with previous operator.



Inspection Photos
Location Name: Lind 23-15
Location ID: 414362



Photo 5: Battery sign needs labeling replaced

