

Inspection Photos
Location Name: Hirsch Pad
Location ID: 414362



Photo 1: Tank Battery



Photo 2: Unused risers

Inspection Photos
Location Name: Hirsch Pad
Location ID: 414362



Photo 3: Unused risers



Photo 4: Unused risers

Inspection Photos
Location Name: Hirsch Pad
Location ID: 414362



Photo 5: Unused risers



Photo 6: Unused risers

Inspection Photos
Location Name: Hirsch Pad
Location ID: 414362



Photo 7: Trash in gas meter house.




Photo 8: Unused equipment in separator house.



Inspection Photos
Location Name: Hirsch Pad
Location ID: 414362



Photo 9: No BBLS on produced water tank.



Photo 10: No NFPA placard/BBLS on produced water tank



Inspection Photos
Location Name: Hirsch Pad
Location ID: 414362



Photo 11: No labeling on tank (BBLS/contents)



Photo 12: No labeling on tank (BBLS/contents)