

Pit Status Evaluation Form

Pit Overview:

Pit Name: Schrack 1	Facility ID: 118034
Current Status: Unknown	Status Date: 09/23/1999
Current Operator: Tindall Operating Company 88380	
Updated Operator: Sunset Plugging & Equipment Inc 84935 (eff 1/1/1993)	
Form 15 Pit Permit Doc #: 383743	Permit Date: 11/15/1976
Related Facilities: Schrack V #1 well API 05-123-07999 (Facility 240211); Location ID 406204	

County: Weld			
Township: 8N	Range: 56W	Section: 10	QQ: NWSE
Original Latitude/ Longitude: 40.673687 / -103.625848			
Updated Latitude/ Longitude: /			
Basis for Location Change:			
No visible pit in aerials to 1999, location not changed			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | |
|--|------------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 383743 | Date: 11/15/1976 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 383745 | Date: 04/30/1985 |
| Doc #: 383746 | Date: 06/23/1986 |
| Doc #: 239609 | Date: 12/19/1995 |
| <input type="checkbox"/> Form 27 Remediation Workplan – Project #: | Date: |
| <input checked="" type="checkbox"/> Form 4 Sundry Notice – Doc #: 239610 | Date: 8/15/1995 |
| <input type="checkbox"/> COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 07/17/1995

Timing of Pit Closure:

Pit closed with plugging and abandonment of well in July 1995

Pit Status Review Summary:

Pits were closed in accordance with COGCC Rules in effect at time of pit closure; site has passed final reclamation inspection